

# Inspection Photos

10/25/2021

Operator: TEP ROCKY MOUNTAIN LLC #  
96850

Location ID: 439173  
Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC # 96850  
Location ID: 439173



**Photo 1:** Photos show the sediment traps on the NW/NE corners of the production area. Photos show controls have not been installed in accordance with good engineering practices to allow for proper stormwater discharge.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC # 96850  
Location ID: 439173



**Photo 2:** Photos provide examples showing that control measures to protect and stabilize the cut slopes of the Location remain missing or insufficient.

**Inspection Photos**  
**Operator Name: TEP ROCKY MOUNTAIN LLC # 96850**  
**Location ID: 439173**



**Photo 3:** Photo shows signage has been installed at Location's entrance.

