

Inspection Photos
Location Name: Pappenheim 6-62-23 PAD
Location ID: 432757



Photo 1 – Pumping Unit

Photo 2 – Risers Marked

Inspection Photos
Location Name: Pappenheim 6-62-23 PAD
Location ID: 432757



Photo 3 – Risers Marked

Photo 4 – Unmarked Riser South on VRUs

Inspection Photos
Location Name: Pappenheim 6-62-23 PAD
Location ID: 432757



Photo 5 – VRUs – Stained Soil at East Unit

Photo 6 – Risers marked

Inspection Photos
Location Name: Pappenheim 6-62-23 PAD
Location ID: 432757



Photo 7 – Tank Battery Signs

Photo 8 – Tank Battery

Inspection Photos
Location Name: Pappenheim 6-62-23 PAD
Location ID: 432757



Colorado Oil and Gas Conservation Commission
40.47993, -104.29197, 4643.1ft, 58°
10/25/2021 11:49:52

Photo 9 – ECDs