

Inspection Photos
Operator: Simcoe
API: 067-08809
Date: 10/27/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Culvert needs to be removed and properly disposed of.



Photo 3. View of the eastern project area, facing southward. Cattle grazing onsite at time of inspection, revegetation should be assessed during active growing season.



Photo 4. View of the reference area comprised of irrigated grass field with grasses such as meadow brome, orchard grass, perennial rygrass, as well as wetland vegetation such as cattails, rushes, and foxtail barley.