

Inspection Photos
Location Name: Pete Montoya B2
Location ID: 318386



Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: Pete Montoya B2
Location ID: 318386



Photo 3 weeds have been cut around equipment. pump jack

Photo 4 weeds have been cut around ancillary equipment