

Inspection Photos
Location Name: Vonasek 1
Location ID: 333302



Photo 1 WH sign buried by weeds

Photo 2 pump jack parts

Inspection Photos
Location Name: Vonasek 1
Location ID: 333302



Photo 3 pump jack parts in Dead weeds

Photo 4 pump jack parts dead weeds

Inspection Photos
Location Name: Vonasek 1
Location ID: 333302



Photo 5 access rd. overgrown with dead weeds



Photo 6 TB sign

Inspection Photos
Location Name: Vonasek 1
Location ID: 333302



Photo 7 TB placard missing from crude tank

Photo 8 Stained soil by crude tank load out line

Inspection Photos
Location Name: Vonasek 1
Location ID: 333302




Photo 9 Bird protector missing from Heater Treater stack



Photo 10 Bird protector sitting on the ground next to the Heater Treater

Inspection Photos
Location Name: Vonasek 1
Location ID: 333302




Photo 11 Heater Treater



Photo 12 Stained soil has been cleaned up around Heater Treater and gravel covered inside the frame of the Treater

Inspection Photos
Location Name: Vonasek 1
Location ID: 333302



**Photo 13 stained soil has been cleaned around Heater
Treater**

Photo 14 Vertical Separator

Inspection Photos
Location Name: Vonasek 1
Location ID: 333302




Photo 15 Gas Meter Run