

## Inspection Photos

Location Name: Amoco-Charter-Schneider UA #12

Location ID: 318411



Photo 1 well head and debris: dead weeds.



Photo 2 Debris and no well head sign.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Amoco-Charter-Schneider UA #12

Location ID: 318411



Photo 3 Debris: dead weeds around electric panel



Photo 4 Debris: dead weeds and no well head sign.