

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402851623

Date Received:

10/25/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87401

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name Phone

Rowley, Darren

Email

drowley@logosresourcesllc.com

regulatory@logosresourcesllc.com

Fischer, Alex

alex.fischer@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 688800992

Inspection Date: 08/27/2021

FIR Submit Date: 09/03/2021

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC

Company Number: 10679

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87401

LOCATION - Location ID: 312051

Location Name: BONDAD 33-9-N33N9W Number: 2SESW County: LA PLATA

Qtrqr: SESW Sec: 2 Twp: 33N Range: 9W Meridian: N

Latitude: 37.129100 Longitude: -107.799440

FACILITY - API Number: 05-067-00 Facility ID: 216532

Facility Name: BONDAD 33-9 Number: 22A

Qtrqr: SESW Sec: 2 Twp: 33N Range: 9W Meridian: N

Latitude: 37.129100 Longitude: -107.799440

CORRECTIVE ACTIONS:

1 ☒ CA# 155525

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a. Per Rule 912.e.(1) the operator will submit a supplemental Form 19 to close Spill/Release Point ID #480361 with work proceeding under REM Project #19542.

Date: 10/01/2021

Response: CA COMPLETED

Date of Completion: 09/23/2021

Mr. Hughes was contacted on 7/29/2021 to report the release. All free liquids and contaminated soil associated

Operator Comment: with this release were cleaned up, removed and properly disposed of by a hydrovac truck on 7/30/2021. per Rule 912.a. and Per Rule 912.e.(1) Logos Operating will submit a supplemental Form 19 to close the Spill/Release Point ID #480361 with work proceeding under REM Project #19542. Logos Operating along with Mr. Hughes agreed that removing the BGT would be the best solution for prevention in the future, as the well is temporarily abandoned. The BGT was removed and soil samples taken please see test results included in this message.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2 ☒ CA# 155526

Corrective Action: Provide a Supplemental Form 27 to update project file with analytical results and work conducted.

Date: 10/01/2021

Response: CA COMPLETED

Date of Completion: 10/25/2021

Operator Comment: A sample was taken at the Bondad 33 9 22A on 8/10/2021 and LOGOS received the Analytical Report on 8/20/2021.

COGCC Decision: Approved

COGCC Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Marie E FLorez

Signed: \_\_\_\_\_

Title: Regulatory Specialist

Date: 10/25/2021 10:21:01 AM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
402851623	FIR RESOLUTION SUBMITTED
402851640	After initial clean up 1
402851641	After initial clean up 2
402851643	After initial clean up 3

Total Attach: 4 Files