

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402815419

Date Received:  
09/17/2021

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 10651

Name of Operator: VERDAD RESOURCES LLC

Address: 1125 17TH STREET SUITE 550

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Michael Cugnetti

7208456901

mcugnetti@verdadresources.com

**COGCC INSPECTION SUMMARY:**

FIR Document Number: 696303567

Inspection Date: 09/09/2021

FIR Submit Date: 09/09/2021

FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: VERDAD RESOURCES LLC

Company Number: 10651

Address: 1125 17TH STREET SUITE 550

City: DENVER State: CO Zip: 80202

**LOCATION - Location ID: 434893**

Location Name: Castor Number: 4-36-9-59 County: \_\_\_\_\_  
PAD

Qtrqtr: NENE Sec: 36 Twp: 9N Range: 59W Meridian: 6

Latitude: 40.713510 Longitude: -103.918960

**FACILITY - API Number: 05-123- -00 Facility ID: 434893**

Facility Name: Castor Number: 4-36-9-59  
PAD

Qtrqtr: NENE Sec: 36 Twp: 9N Range: 59W Meridian: 6

Latitude: 40.713510 Longitude: -103.918960

**CORRECTIVE ACTIONS:**

1 ☒ CA# 155681

Corrective Action: For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."  
Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 09/24/2021

Response: CA COMPLETED

Date of Completion: 09/15/2021

Tightened the treater burner tube gasket and took out a seeping gauge on the wellhead and plugged it. All

Operator Comment: stained soil at the heater treater and well head was removed and properly disposed of. See attached photo documentation of corrective actions.

COGCC Decision: Approved

COGCC Representative: Approved

2 ☒ CA# 155682

Corrective Action: Install sign to comply with Rule 605.h.

Date: 10/11/2021

Response: CA COMPLETED

Date of Completion: 09/15/2021

Operator Comment: NFPA Label on South Produced Water Tank was replaced. See attached photo documentation of corrective actions.

COGCC Decision: Approved

COGCC Representative: Approved

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Cugnetti

Signed:

Title: Director of EHS&R

Date: 9/17/2021 1:55:13 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402815419	FIR RESOLUTION SUBMITTED
402815460	corrective action photo documentation
402815463	corrective action photo documentation
402815465	corrective action photo documentation

Total Attach: 4 Files