

Inspection Photos
Location Name: Chavez #1
API: 05-007-06120



Chavez #1 location photo. Equipment stored on site including fencing material and gooseneck trailer.



Chavez #1 pump jack and location sign.

Inspection Photos
Location Name: Chavez #1
API: 05-007-06120



Chavez #1 well head. Absorbent granules have been spread over impacted soil.



Container with oily contents near supply shed.

Inspection Photos
Location Name: Chavez #1
API: 05-007-06120



Open topped container with oily contents.



300 bbl. crude oil AST for Chavez #1 and #2.