

Inspection Photos
Location Name: Nielson #4
API: 05-007-06117



Nielson #4 pump jack and well head. Pump jack was operating during this inspection.



Well head and polished rod are wet and stained with oil.

Inspection Photos
Location Name: Nielson #4
API: 05-007-06117



Nielson #4 AST. Uncompacted earthen berm around tank battery.



Fencing material adjacent to secondary containment berm.

Inspection Photos
Location Name: Nielson #4
API: 05-007-06117



Tank battery sign has been updated to include information required by Inspection Document #688800881.

AST has been attached to anchors.