

Inspection Photos
Location Name: Nielson #3
API: 05-007-06116



Nielson #3 location photo.



Nielson #3 pump jack and well head.

Inspection Photos
Location Name: Nielson #3
API: 05-007-06116



Nielson #3 tank battery.



ASTs have been connected to anchors with steel cable.