

Inspection Photos  
Operator: Simcoe  
API: 067-08862  
Date: 10/27/2021



Photo 1. View of the project area from the well pad entrance facing center.





Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with western wheatgrass, sand dropseed, and crested wheatgrass. Well pad vegetation is mowed.





Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4. View of reference area comprised of sagebrush shrubland with native and introduced grasses and forbs such as goldenaster, snakeweed, western wheatgrass, and crested wheatgrass.