


Location ID: 431634



Inspection Photos
Location Name: Buchner 2-2 H
Location ID: 431634



Photo 3 – Stained Soil at Eastside of Gearbox



Photo 4 – Stained Soil at Eastside of Gearbox

Inspection Photos
Location Name: Buchner 2-2 H
Location ID: 431634



Photo 5 – Stained Soil at Gas Engine



Photo 6 – Stained at Westside of Gearbox

Inspection Photos
Location Name: Buchner 2-2 H
Location ID: 431634



Photo 7 – Flare and ECD



Photo 8 – Concrete Vault Removed



Inspection Photos
Location Name: Buchner 2-2 H
Location ID: 431634



Photo 9 – Heater Treater



Photo 10 – Tank Battery Sign

Inspection Photos
Location Name: Buchner 2-2 H
Location ID: 431634



Colorado Oil and Gas Conservation Commission
40.60331, -104.06724, 4868.7ft, 138°
10/25/2021 13:25:37

Photo 11 – Tank Battery



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources