

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/27/2021

Submitted Date:

10/27/2021

Document Number:

701102109

FIELD INSPECTION FORM

Loc ID 334546	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 29 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: 10433 Name of Operator: LARAMIE ENERGY LLC Address: 1001 17TH STREET #1900 City: DENVER State: CO Zip: 80202				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
COGCC, Laramie	970-248-0497	cogccnotifications@laramie-energy.com	All inspections

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283005	WELL	TA	03/01/2021	GW	077-09011	GUNDERSON 13-13	TA
283006	WELL	PR	09/01/2018	GW	077-09010	GUNDERSON 13-11	PR
283007	WELL	PR	05/07/2020	GW	077-09009	GUNDERSON 13-12	PR
283008	WELL	SI	11/01/2020	GW	077-09008	GUNDERSON 13-14	SI
283009	WELL	PR	07/18/2018	GW	077-09007	GUNDERSON 13-5	PR
283010	WELL	PR	06/24/2008	GW	077-09006	GUNDERSON 13-6	PR
453261	WELL	PR	08/30/2018	OW	077-10527	Gunderson 0994-13-15E	PR
453262	WELL	PR	09/30/2018	OW	077-10528	Gunderson 0994-14-16E	PR
453263	WELL	PR	08/27/2018	OG	077-10529	Gunderson 0994-13-17E	PR
453264	WELL	PR	09/25/2018	OW	077-10530	Gunderson 0994-14-17E	PR
453265	WELL	PR	07/01/2018	OG	077-10531	Gunderson 0994-13-11W	PR
453266	WELL	PR	08/30/2018	OW	077-10532	Gunderson 0994-13-16E	PR
453267	WELL	PR	09/25/2018	OW	077-10533	Gunderson 0994-14-12E	PR
453268	WELL	PR	09/22/2018	OW	077-10534	Gunderson 0994-13-12W	PR
453269	WELL	PR	08/30/2018	OW	077-10535	Gunderson 0994-13-12E	PR
453270	WELL	PR	09/04/2018	OW	077-10536	Gunderson 0994-13-16W	PR
453271	WELL	PR	07/01/2018	OG	077-10537	Gunderson 0994-13-05W	PR
453272	WELL	PR	09/25/2018	OW	077-10538	Gunderson 0994-14-11E	PR
453273	WELL	PR	07/01/2018	OW	077-10539	Gunderson 0994-13-10E	PR
453274	WELL	PR	09/29/2018	OW	077-10540	Gunderson 0994-14-15E	PR
453275	WELL	PR	09/21/2018	OG	077-10541	Gunderson 0994-13-06W	PR

453276	WELL	PR	08/27/2018	OG	077-10542	Gunderson 0994-13-15W	PR
453277	WELL	PR	09/21/2018	OW	077-10543	Gunderson 0994-14-10E	PR
453278	WELL	PR	07/01/2018	OG	077-10544	Gunderson 0994-13-07W	PR
453279	WELL	PR	07/29/2018	OW	077-10545	Gunderson 0994-13-04W	PR
453280	WELL	PR	07/01/2018	OG	077-10546	Gunderson 0994-13-10W	PR
453281	WELL	PR	08/27/2018	OW	077-10547	Gunderson 0994-13-17W	PR

General Comment:

COGCC Routine Inspection Report Summary

Location is in a High Priority Habitat Area.

During this inspection the following compliance issues were observed:

- No labeling on separator glycol tanks.

3- 4 unit vertical heated separators with glycol vessel approximately 72"x48"x159". Approximately 56.6 bbls

1- 5 unit vertical heated separator with a simular but larger capacity.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	No labeling on separator glycol tanks. 3- 4 unit vertical heated separators with glycol vessel approximately 72"x48"x159". Approximately 56.6 bbls 1- 5 unit vertical heated separator with a similar but larger capacity.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	01/31/2022

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 14		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 17		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 14		

Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	1000 gallons	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	7	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	283005	Type:	WELL	API Number:	077-09011	Status:	TA	Insp. Status:	TA
<div>Producing Well</div> <div> <div>Comment:</div> <div>Producing well</div> </div> <div> <div>Corrective Action:</div> <div></div> </div> <div> <div>Date:</div> <div></div> </div>									
Facility ID:	283006	Type:	WELL	API Number:	077-09010	Status:	PR	Insp. Status:	PR
<div>Producing Well</div> <div> <div>Comment:</div> <div>Producing well</div> </div> <div> <div>Corrective Action:</div> <div></div> </div> <div> <div>Date:</div> <div></div> </div>									
Facility ID:	283007	Type:	WELL	API Number:	077-09009	Status:	PR	Insp. Status:	PR
<div>Producing Well</div> <div> <div>Comment:</div> <div>Producing well</div> </div> <div> <div>Corrective Action:</div> <div></div> </div> <div> <div>Date:</div> <div></div> </div>									
Facility ID:	283008	Type:	WELL	API Number:	077-09008	Status:	SI	Insp. Status:	SI
Facility ID:	283009	Type:	WELL	API Number:	077-09007	Status:	PR	Insp. Status:	PR
<div>Producing Well</div> <div> <div>Comment:</div> <div>Producing well</div> </div> <div> <div>Corrective Action:</div> <div></div> </div> <div> <div>Date:</div> <div></div> </div>									
Facility ID:	283010	Type:	WELL	API Number:	077-09006	Status:	PR	Insp. Status:	PR
<div>Producing Well</div> <div> <div>Comment:</div> <div>Producing well</div> </div> <div> <div>Corrective Action:</div> <div></div> </div> <div> <div>Date:</div> <div></div> </div>									
Facility ID:	453261	Type:	WELL	API Number:	077-10527	Status:	PR	Insp. Status:	PR
<div>Producing Well</div> <div> <div>Comment:</div> <div>Producing well</div> </div> <div> <div>Corrective Action:</div> <div></div> </div> <div> <div>Date:</div> <div></div> </div>									
Facility ID:	453262	Type:	WELL	API Number:	077-10528	Status:	PR	Insp. Status:	PR
<div>Producing Well</div> <div> <div>Comment:</div> <div>Producing well</div> </div> <div> <div>Corrective Action:</div> <div></div> </div> <div> <div>Date:</div> <div></div> </div>									
Facility ID:	453263	Type:	WELL	API Number:	077-10529	Status:	PR	Insp. Status:	PR
<div>Producing Well</div> <div> <div>Comment:</div> <div>Producing well</div> </div> <div> <div>Corrective Action:</div> <div></div> </div> <div> <div>Date:</div> <div></div> </div>									

Facility ID:	453264	Type:	WELL	API Number:	077-10530	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	453265	Type:	WELL	API Number:	077-10531	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	453266	Type:	WELL	API Number:	077-10532	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	453267	Type:	WELL	API Number:	077-10533	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	453268	Type:	WELL	API Number:	077-10534	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	453269	Type:	WELL	API Number:	077-10535	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	453270	Type:	WELL	API Number:	077-10536	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	453271	Type:	WELL	API Number:	077-10537	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	453272	Type:	WELL	API Number:	077-10538	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	453273	Type:	WELL	API Number:	077-10539	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	453274	Type:	WELL	API Number:	077-10540	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	453275	Type:	WELL	API Number:	077-10541	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	453276	Type:	WELL	API Number:	077-10542	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	453277	Type:	WELL	API Number:	077-10543	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	453278	Type:	WELL	API Number:	077-10544	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	453279	Type:	WELL	API Number:	077-10545	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	453280	Type:	WELL	API Number:	077-10546	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	453281	Type:	WELL	API Number:	077-10547	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
Ditches						
Gravel						
		Ditches				
Berms						
		Gravel				
		Compaction				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402855292	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5566044
701102110	Inspection 701102109 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5566039