

Final Reclamation Inspection

October 14th, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 302170

Inspection Document #: 701900200

Weld County, CO

NENE Section 31 T7N R63W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Zahourek 41-31
Location ID: 302170



Photo 1. 2016 aerial imagery of the well pad and tank battery (north is up).

Inspection Photos
Location Name: Zahourek 41-31
Location ID: 302170



Photo 2. Overview photo of the well pad taken at ground level from the south edge looking north. Note: well pad falls on the edge of a crop field which had recently been mowed and covered with mulch. Will need to re-inspect when vegetation has re-established



Inspection Photos
Location Name: Zahourek 41-31
Location ID: 302170



Photo 3. Overview photo of the tank battery taken from the north edge looking south. See description under photo 2.