

**Inspection Photos**  
**Location Name: NC Farms 16-32**  
**Location ID: 426843**



**Photo 1 Well heads. 16-32 missing well head sign**



**Photo 2 loc pic**

**Inspection Photos**  
**Location Name: NC Farms 16-32**  
**Location ID: 426843**



**Photo 3 TNK BTRY**



**Photo 4 production equipment**



Inspection Photos  
Location Name: NC Farms 16-32  
Location ID: 426843




Photo 5 KIM RAY valve leaking



Photo 6 Stained soil around compressor skid.