

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/03/2021

Submitted Date:

11/03/2021

Document Number:

693505735

FIELD INSPECTION FORM

Loc ID 477361 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
478564	WELL	DG	09/30/2021		123-51330	Roth A32-760	DG

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	DRILLING/RECOMP		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Sound walls all four sides		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 478564 Type: WELL API Number: 123-51330 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: H&P 517 Pusher/Rig Manager: Dave Nelson
 Permit Posted: SATISFACTORY Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: Pass Test Pressure PSI: 5000 Safety Plan: YES

Drill Fluids

Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____
 Multi-Well: YES Disposal Location: Waste Management

Comment: At time of inspection rig had TD night befor and was rigging and hauling out rig.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<u>Routine inspection.</u>	silverr	11/03/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693505736	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5571331