



WELLHEAD ABANDONMENT FORM

SITE NAME: Benson Farms 12N-23HZ							DATE: 8/5/2021	REM. PROJECT #:	WEATHER: Sunny 80		
SITE DIRECTIONS: ST HWY 66 and CR 9 1/2 NORHT 0.5, EAST 0.5 SOUTH .1 INTO							CLIENT: Oxy				
LEGALS AND LAT/LONG: 40.210079, -104.960574							TASMAN PERSONNEL: Brandon LeVasseur				
SOIL TYPES: Lean Clay - CL							SURFACE GRADIENT: South				
SOIL SAMPLING							FACILITY INFRASTRUCTURE				
Date/Time	Soil Sample ID	PID (ppm)	Visual	Olfactory	Photo?	Grab or Lab Sample?	EQUIPMENT		Quantity		
							Above Ground Storage Tank (AST)				
8/5/2021 12:07	WH-B01@6'	7.0	No Staining	No Odor	Yes	Lab	Buried or Partially Buried Vessel				
8/5/2021 12:08	WH-N01@5'	1.8	No Staining	No Odor	Yes	N/A	Separator				
8/5/2021 12:09	WHS01@5'	4.4	No Staining	No Odor	Yes	N/A	Emission Control Device (ECD)				
8/5/2021 12:10	WH-E01@5'	2.1	No Staining	No Odor	Yes	N/A	Dump Line				
8/5/2021 12:11	WH-W01@5'	1.5	No Staining	No Odor	Yes	N/A	Wellhead		1		
8/5/2021 12:12	WHS-N01@3"	2.6	No Staining	No Odor	Yes	N/A	Flowline				
8/5/2021 12:13	WHS-S01@3"	2.0	No Staining	No Odor	Yes	N/A	Other:				
8/5/2021 12:14	WHS-E01@3"	0.8	No Staining	No Odor	Yes	N/A	Soil Loads Removed				
8/5/2021 12:15	WHS-W01@3"	0.7	No Staining	No Odor	Yes	N/A	IMPACTED SOIL IDENTIFIED?				
8/5/2021 12:16	WH-BG01@3'	0.6	No Staining	No Odor	Yes	Lab	ESTIMATED VOLUME OF IMPACTS:				
8/5/2021 12:17	WH-BG01@6'	1.6	No Staining	No Odor	Yes	Lab	Date		Number	CY	
8/5/2021 12:18	WH-BG02@3'	1.6	No Staining	No Odor	Yes	Lab					
8/5/2021 12:19	WH-BG02@6'	1.0	No Staining	No Odor	Yes	Lab					
8/6/2021 09:57	WH-N02@5'	1.7	No Staining	No Odor	Yes	Lab					
8/6/2021 09:58	WH-S02@5'	3.7	No Staining	No Odor	Yes	Lab					
8/6/2021 09:59	WH-E02@5'	1.7	No Staining	No Odor	Yes	Lab	Total Removed		0	0	
8/6/2021 10:00	WH-W02@5'	1.2	No Staining	No Odor	Yes	Lab	Disposal Facility:				
10/22/2021 13:35	WH-B02@9'	3.4	No Staining	No Odor	Yes	Lab	Groundwater Recovery				
10/22/2021 13:37	WH-S03@8'	2.0	No Staining	No Odor	Yes	Lab	DATE GW ENCOUNTERED:		DEPTH:		
10/22/2021 13:39	WH-E03@8'	1.6	No Staining	No Odor	Yes	Lab	GROUNDWATER IN CONTACT WITH IMPACTED SOIL?				
10/22/2021 13:41	WH-W03@8'	4.6	No Staining	No Odor	Yes	Lab					
							LNAPL OR SHEEN OBSERVED ON GW?				
GROUNDWATER SAMPLING							Date		BBLs		
Date/Time	Groundwater Sample ID	Depth Collected	Turbid?	Sheen?	Odor?	Photo?					
							Total Removed		0		
							Disposal Facility:				

Photographic Log

							
Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions:			

Photographic Log

							
Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:		Volume:		Material:		Volume:	
Contents:				Contents:			
Notes/Conditions:				Notes/Conditions:			

Photographic Log



Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions: 080621 sample locations				Notes/Conditions: Soil screening and sampling location 102221			