

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402862184

Date Received:
11/04/2021

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
General		sjninspections@ikavenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903784

Inspection Date: 10/22/2021

FIR Submit Date: 10/25/2021

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 325088

Location Name: WILDE GAS UNIT B-N33N8W Number: 36NENW County: LA PLATA

Qtrqtr: NENW Sec: 36 Twp: 33N Range: 8W Meridian: N

Latitude: 37.064918 Longitude: -107.672129

FACILITY - API Number: 05-067-00 Facility ID: 213966

Facility Name: WILDE B Number: 1

Qtrqtr: NENW Sec: 36 Twp: 33N Range: 8W Meridian: N

Latitude: 37.064918 Longitude: -107.672129

CORRECTIVE ACTIONS:

1 CA# 157115

Corrective Action: -Control weeds by 11/15/2021. Subsequent treatments will be needed due to seeding condition observed.

Date: 11/15/2021

Response: CA COMPLETED

Date of Completion: 11/02/2021

Operator Comment: site has been treated

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA Completed

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Karin Rhodes

Signed: _____

Title: admin asst

Date: 11/4/2021 10:12:01 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402862190	map of infestation at site
402862193	work completed

Total Attach: 2 Files