

Inspection Photos
Operator: Simcoe
API: 067-06663
Date: 10/29/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing similar to reference area, largely in a grazed condition with scattered perennial grasses such as crested wheatgrass.



Photo 4. View of reference area comprised of open grass field, largely in a grazed vegetative condition, with grasses such as western wheatgrass and smooth brome.