

Inspection Photos

11/05/2021

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 334156

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334156



Photo 1: Photos provide examples showing control measures to protect and stabilize the soil stockpiles on the location remain missing or insuffcieint.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334156



Photo 2: Photos taken from the sediment trap on the west end of the Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334156



Photo 3: Continued from photo 2. Photo shows Operator has repaired erosion on the east end of the trap, however soils have been left unconsolidated; control measures to stabilize slopes of the sediment trap remain missing or insufficient.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334156



Photo 4: Photos shows the outlet from the production area leading into the sediment trap is improperly armored and missing geotextile lining per good engineering practices.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334156



Photo 5: Photo example showing trap has been constructed with steep slopes; rill erosion evident; control measures to stabilize/protect slopes remain missing or insufficient.