

# Inspection Photos

11/05/2021

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 323866

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location ID: 323866



**Photo 1:** Photo shows wildlife protection devices to prevent wildlife access to the containment BMP remains missing or insufficient.





Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location ID: 323866



**Photo 2:** Photo taken from the stormwater diversion ditch on the west end of the Location, facing north. Photo shows that the stormwater diversion ditch remains improperly constructed with an outlet, to prevent offsite degradation due to runoff.



Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location ID: 323866



**Photo 3:** Photos taken north of the ditch. Photo shows offsite erosion degradation due to improper stormwater runoff controls on the Location.