

Inspection Photos  
Location Name: Shoveler PAD  
Location ID: 455365



Photo 1 – Sign at Entrance



Photo 2 – Capacity Label installed



Inspection Photos  
Location Name: Shoveler PAD  
Location ID: 455365



Colorado Oil and Gas Conservation Commission  
40 63932, -104 11857, 4895.6ft, 143°  
11/03/2021 13:59:59

Photo 3 – NFPA Label missing



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources