

# Inspection Photos

API: 071-06347

Operator: OGRIS OPERATING LLC

Inspection Date: 11/8/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-06347 | Date: 11/8/2021

## Inspection Photos



**Photo 1.** The road was regraded and additional gravel was spread along areas of the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06347 | Date: 11/8/2021



## Inspection Photos



**Photo 2.** The road was regraded and additional gravel was spread along areas of the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06347 | Date: 11/8/2021



## Inspection Photos



**Photo 3.** The culvert near the location on the main road is still filled in with sediment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06347 | Date: 11/8/2021



## Inspection Photos



**Photo 4.** Facing southeast toward the access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06347 | Date: 11/8/2021



## Inspection Photos



**Photo 5.** Facing toward the well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06347 | Date: 11/8/2021