

Inspection Photos

API: 071-09283

Operator: OGRIS OPERATING LLC

Inspection Date: 11/8/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09283 | Date: 11/8/2021

Inspection Photos



Photo 1. Facing southwest along the access road. The road was regraded and additional gravel was spread along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09283 | Date: 11/8/2021

Inspection Photos



Photo 2. Facing back down the road. This steep area of the roadside needs additional BMPs' to prevent erosion and sediment accumulation at the culverts.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09283 | Date: 11/8/2021

Inspection Photos



Photo 3. Facing southwest along the access road. The road was regraded and additional gravel was spread along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09283 | Date: 11/8/2021

Inspection Photos



Photo 4. Facing toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09283 | Date: 11/8/2021