

**Inspection Photos**  
**Location Name: Timbro 9B PAD**  
**Location ID: 456879**



**Photo 1 – Sign at Entrance**



**Photo 2 – Tank Battery**



**Inspection Photos**  
**Location Name: Timbro 9B PAD**  
**Location ID: 456879**



**Photo 3 – Separators, ECD and VRU**



**Photo 4 – Compressor**



**Inspection Photos**  
**Location Name: Timbro 9B PAD**  
**Location ID: 456879**



**Photo 5 – Wellheads**



**Photo 6 – Separators**



**Inspection Photos**  
**Location Name: Timbro 9B PAD**  
**Location ID: 456879**



**Photo 7 – Weeds in I.R. Area**



**Photo 8 – Weeds in I.R. Area**



**Inspection Photos**  
**Location Name: Timbro 9B PAD**  
**Location ID: 456879**



**Photo 9 – Weeds in I.R. Area**



**Photo 10 – Weeds in I.R. Area**

**Inspection Photos**  
**Location Name: Timbro 9B PAD**  
**Location ID: 456879**



**Photo 11 – Weeds in I.R. Area**

