

Inspection Photos

API: 071-06218

Operator: MERIDIAN OIL INC

Inspection Date: 11/8/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06218 | Date: 11/8/2021

Inspection Photos



Photo 1. Facing southwest toward the reclaimed location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06218 | Date: 11/8/2021

Inspection Photos



Photo 2. Facing south toward the location. The perennial vegetation is progressing throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06218 | Date: 11/8/2021

Inspection Photos



Photo 3. Facing southeast toward the location. The perennial vegetation is progressing throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06218 | Date: 11/8/2021

Inspection Photos



Photo 4. Facing northeast at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06218 | Date: 11/8/2021

Inspection Photos



Photo 5. This area along the upper slope consists of Cheat grass. Perennial vegetation will need to establish more in this area and may require additional reseeding.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06218 | Date: 11/8/2021

Inspection Photos



Photo 6. Standing at upper east side of the location. Perennial vegetation will need to establish more in this area and may require additional reseeding.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06218 | Date: 11/8/2021

Inspection Photos



Photo 7. North side across the road facing east. Perennial vegetation will need to establish more in this area and may require additional reseeding.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06218 | Date: 11/8/2021