

Inspection Photos
Location Name: Wandell 21-7
Location ID: 330812



Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: Wandell 21-7
Location ID: 330812



Photo 3 TB sign

Photo 4 TB

Inspection Photos
Location Name: Wandell 21-7
Location ID: 330812



Photo 5 Methanol tank




Photo 6 Horiz. Heated Sep.

Inspection Photos

Location Name: Wandell 21-7
Location ID: 330812



Colorado Oil & Gas Conservation Commission
6423 Thistle Ridge Ave, Longmont, CO 80504, USA
40.15782, -104.93454, 4812.2ft, 282°
11/09/2021 10:04:49



Station #	Ad	Gr	Station Name	Sec	Township	Range
330812	W	7	Wandell 21-7	7	21	7
Radio #	Producer Name		Mtr. Tube Size			
1111111	Crown Peak		3/16"			
Transmitter / Module #	Federal #		County			
			State			
Stroke / Span	Unit / Den	Dist / Span	Temp / Span	Altitude	API #	
0.000 / 100	100	0.250	0.25	11.2		
Test Date	OP Size	Beta	Sample Date	H/S	Sample Date	H/S
11-25-21	1.25	117	11-25-21			
11-20-21	1.25		11-20-21	Span		
11-16-21	1.25		11-16-21	Span		
11-25-21	1.25		11-25-21	Span		

Colorado Oil & Gas Conservation Commission
10867 Ebony St, Longmont, CO 80504, USA
40.15794, -104.93454, 4824.2ft, 227°
11/09/2021 10:05:07

Photo 7 Gas Meter Run

Photo 8 Card in meter house indicates current calibration

Inspection Photos
Location Name: Wandell 21-7
Location ID: 330812




Photo 9 ECDs