

Inspection Photos
Location Name: McCallum Unit 50
Location ID: 324610



Photo 1. No bradenhead access apparent.

Form 21
State of Colorado
Oil and Gas Conservation Commission
MECHANICAL INTEGRITY TEST

Well Name: PRREB
Well ID: 844-862
Well Type: INJECTION WELL

Operator: KIP KALITZMAN COMPANY INC.
Wellhead: 303-903-5513
Wellhead ID: 900 Dr. 900 Dr.

Inspector: Reese Elvick
Date: 11-9-21

Signature: [Signature]
Title: The Field Inspector
Date: 11/11/21

Photo 2. Photo of Form 21 as filled out and signed in the field.