

Inspection Photos
Operator: Simcoe
API: 067-07455
Date: 11/3/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Vegetation is established here with smooth brome, sand dropseed, and cattails along irrigation ditch.



Photo 3. View of the southern project area from the southwestern corner facing eastward.



Photo 4. View of the weed debris (up to 4ft tall) and bucket debris on the well pad.



Photo 4. View of reference area comprised of irrigated grass field. Grasses are mowed.