

Inspection Photos
Operator: Simcoe
API: 067-07265
Date: 11/3/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with rubber rabbitbrush, sand dropseed, and western wheatgrass, largely in a grazed vegetative condition at this time.



Photo 3. View of the southern project area from the southwestern corner facing southeastward.



Photo 4. View of reference area comprised of open pasture with grasses and forbs largely in a grazed condition at this time.