

## Inspection Photos

Location Name: 29-4N-64W NWNE Johnson RC TB

Facility ID: 481073



**Photo #1 Tank Battery**



**Photo #2 Production Equipment**

## Inspection Photos

Location Name: 29-4N-64W NWNE Johnson RC TB

Facility ID: 481073



**Photo #3 Unmarked Riser**

**Photo #4 Stained soil**