

**Inspection Photos**  
**Location Name: Wildhorse 02-0224H**  
**Location ID: 427181**



**Photo 1 – Tank Battery Sign**



**Photo 2 – Tank Battery**



**Inspection Photos**  
**Location Name: Wildhorse 02-0224H**  
**Location ID: 427181**



**Photo 3 – Wellhead**



**Photo 4 – Pumping Unit Weeds**





**Inspection Photos**  
**Location Name: Wildhorse 02-0224H**  
**Location ID: 427181**



**Photo 5 – Stained Soil at Exhaust**



**Photo 6 – Flare and ECD – Weeds**

**Inspection Photos**  
**Location Name: Wildhorse 02-0224H**  
**Location ID: 427181**



**Photo 7 – Heater Treater – Weeds**



**Photo 8 – Heater Treater**



**Inspection Photos**  
**Location Name: Wildhorse 02-0224H**  
**Location ID: 427181**



**Photo 9 – Produced Water Tank missing NFPA, Content and Capacity**