

Inspection Photos
Location Name: Wolf 35-2623H
Location ID: 426053



Colorado Oil and Gas Conservation Commission
40.78778, -103.94785, 4935.0ft, 217°
11/10/2021 13:24:24



Colorado Oil and Gas Conservation Commission
40.78776, -103.9481, 4942.6ft, 165°
11/10/2021 13:25:21

Photo 1 – Tank Battery

Photo 2 – Tank Battery Sign

Inspection Photos
Location Name: Wolf 35-2623H
Location ID: 426053



Colorado Oil and Gas Conservation Commission
40.78776, -103.94806, 4933.8ft, 190°
11/10/2021 13:25:13



Colorado Oil and Gas Conservation Commission
40.78781, -103.94845, 4942.9ft, 235°
11/10/2021 13:30:51

Photo 3 – Labels Upside down and not visible

Photo 4 – Heater Treater – Weeds

Inspection Photos
Location Name: Wolf 35-2623H
Location ID: 426053



Colorado Oil and Gas Conservation Commission
40.78801, -103.94845, 4929.1ft, 157°
11/10/2021 13:31:18



Colorado Oil and Gas Conservation Commission
40.788, -103.94845, 4957.2ft, 140°
11/10/2021 13:31:49

Photo 5 – Risers have been marked

Photo 6 – Pumping Unit – Weeds

Inspection Photos
Location Name: Wolf 35-2623H
Location ID: 426053



Photo 7 – Stained Soil at Gas Engine

Photo 8 – Wellhead – Stained Soil

Inspection Photos
Location Name: Wolf 35-2623H
Location ID: 426053



Photo 9 – Flares