

Inspection Photos
Location Name: Wildhorse 18-1844H
Location ID: 430327



Photo 1 – Pumping Unit

Photo 2 – Exhaust

Inspection Photos
Location Name: Wildhorse 18-1844H
Location ID: 430327



Photo 3 – Stained Soil at Gas Engine

Photo 4 – Stained Soil at Gas Engine

Inspection Photos
Location Name: Wildhorse 18-1844H
Location ID: 430327



Colorado Oil and Gas Conservation Commission
40.7568, -104.01401, 4972.3ft, 309°
11/10/2021 14:02:25

Photo 5 – Oily/Grease Waste



Colorado Oil and Gas Conservation Commission
40.75656, -104.01458, 4956.0ft, 251°
11/10/2021 14:03:16

Photo 6 – ECD and Flare

Inspection Photos
Location Name: Wildhorse 18-1844H
Location ID: 430327



Photo 7 – Heater Treater



Photo 8 – Tank Battery

Inspection Photos
Location Name: Wildhorse 18-1844H
Location ID: 430327



Photo 9 – Tank Battery Sign