

Final Reclamation Inspection

November 8, 2021

Operator: NOBLE ENERGY INC - #100322

Location ID: 309839

Inspection Document #: 697503482

Weld County, CO

NWNE Section 16 T4N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: RYANN STATE C-64N64W /16NWNE

Location ID: 309839



Photo 1. Photo taken from the southern tank battery, facing North. Photo illustrates the establishment of mostly weeds with little to no establishment of desirable species.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697503482

Inspection Photos

Location Name: RYANN STATE C-64N64W /16NWNE

Location ID: 309839



Photo 2. Photo taken from the eastern tank battery, facing North. Photo illustrates the reference area to the left and tank battery to the right.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697503482

Inspection Photos

Location Name: RYANN STATE C-64N64W /16NWNE

Location ID: 309839



Photo 3. Photo taken from the eastern tank battery, facing East. See comments under Photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697503482