

# Final Reclamation Inspection

October 6th, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 327161

Inspection Document #: 701900166

Weld County, CO

SWSW Section 20 T4N R65W

Corey McDonough  
Reclamation Contractor, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Peschel 14-20  
Location ID: 327161



**Photo 1.** 2019 aerial imagery of the well pad and tank battery. Open remediation (9423) associated with PA'd well API # 123-14244. Will need to be re-inspect when remediation has closed.