

Final Reclamation Inspection

October 6th, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 333330

Inspection Document #: 701900167

Weld County, CO

SESW Section 24 T6N R66W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Seeley Lake 1
Location ID: 333330



Photo 1. 2012 aerial imagery of the well pad (north is up). The tank battery highlighted in blue will be associated with the temporarily abandoned well API # 123-23657 highlighted in purple.

Inspection Photos
Location Name: Seeley Lake 1
Location ID: 333330




Photo 2. Overview photo of the well pad, reference area and the TA well (highlighted in purple) taken from the western edge of the crop field with a drone. The photo shows that the well pad appears consistent with the reference area.

Inspection Photos
Location Name: Seeley Lake 1
Location ID: 333330



Photo 3. Ground photo taken from the western edge of the field looking east towards the well pad.