

Final Reclamation Inspection

October 21st, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 323117

Inspection Document #: 701900222

Weld County, CO

SESW Section 22 T5N R65W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Virginia 1-22
Location ID: 323117



Photo 1. 2021 aerial imagery of the well pad, tank battery and access road (north is up).

Inspection Photos
Location Name: Virginia 1-22
Location ID: 323117



Photo 2. overview photo of the well pad. Photo shows that the field has been harvested and will need to be re-inspected during the next growing season.

Inspection Photos
Location Name: Virginia 1-22
Location ID: 323117



Photo 3. Overview photo of the tank battery.