

# Final Reclamation Inspection

November 8, 2021

Operator: NOBLE ENERGY INC - #100322

Location ID: 329752

Inspection Document #: 697503487

Weld County, CO

NWNE Section 16 T4N R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos

Location Name: STATE-64N64W /16NWNE

Location ID: 329752



**Photo 1.** Photo taken from the south tank battery location, facing West. Photo illustrates some tire tracks within the location but had minimal impact on vegetation. Photo also illustrates the location has desirable vegetation throughout.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Number: 697503487

Inspection Photos

Location Name: STATE-64N64W /16NWNE

Location ID: 329752



**Photo 2.** Photo taken from the central tank battery location, facing West. See comments under Photo 1.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Number: 697503487

Inspection Photos

Location Name: STATE-64N64W /16NWNE

Location ID: 329752



**Photo 3.** Photo taken from the central tank battery location, facing Northwest. See comments under Photo 1.



Inspection Photos

Location Name: STATE-64N64W /16NWNE

Location ID: 329752



**Photo 4.** Photo taken from the northern tank battery location, facing East. See comments under Photo 1.



Inspection Photos

Location Name: STATE-64N64W /16NWNE

Location ID: 329752



**Photo 5.** Reference photo taken adjacent to and east of the tank battery, facing East. Photo illustrates the reference area consists mostly of Kochia weeds with some desirable vegetation. The desirable vegetation at the tank battery exceeds that of the reference area.

