

Inspection Photos
Location Name: AL Luft #1
Location ID: 317765



Photo 1 loc pic



Photo 2 loc pic

Inspection Photos
Location Name: AL Luft #1
Location ID: 317765



Photo 3 Access road Small bridge over irrigation ditch



Photo 4 Deck on access road bridge appears to be rotting and creating unsafe conditions.

Inspection Photos
Location Name: AL Luft #1
Location ID: 317765



Photo 5 Land owner had to put dirt on ends of bridge decking to be able to access property.