



- Photo 1 – View northeast to NE corner of Sec 36



- Photo 2 – View southwest toward areas of bare ground



- Photo 3 – Areas of bare ground



- Photo 4 – Areas of bare ground



- Photo 5 – Areas of bare ground



- Photo 6 – Areas of bare ground



- Photo 7 – Areas of bare ground



- Photo 8 – Areas of bare ground



- Photo 9 – Erosion and areas of bare ground



- Photo 10 – Erosion and areas of bare ground



- Photo 11 – Erosion and areas of bare ground



- Photo 12 – Approaching the terminus of impacted area



- Photo 13 –



- Photo 14 –



- Photo 15 – Small pieces of concrete at former location



- Photo 16 – Small pieces of concrete at former production location