

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/16/2021

Submitted Date:

11/16/2021

Document Number:

699104814**FIELD INSPECTION FORM**Loc ID 332791 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections
Dougherty, Tesla		Tesla.Dougherty@chevron.co m	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298854	WELL	PR	07/20/2020	OG	123-29172	HANSCOME C 28-28D	PR
298940	WELL	TA	05/06/2021	OW	123-29209	HANSCOME C 28-29D	TA

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action: _____ Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	Appear to be plumbed to surface		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 298854 Type: WELL API Number: 123-29172 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 08/16/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 3 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 298940 Type: WELL API Number: 123-29209 Status: TA Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: T/A

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 03/11/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary
On Tuesday 11/16/21 at approximately 0802hrs I, Inspector Adam Burns,
Conducted an on-site inspection at Hanscome C-64N64W 28NENW of Noble Energy
Location ID: 332791 in Weld County, Colorado.
While there, I observed one well that is PR and one that is T/A.
No violation of the COGCC rules were observed at the time of inspection.
This is a summary of inspection report.

burnsa

11/16/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
699104815	Inspection Photo	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5581959