

Inspection Photos  
Operator: Simcoe  
API: 067-06338  
Date: 11/11/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing with western wheatgrass, sand dropseed, smooth brome, and crested wheatgrass.





Photo 3. View of the western project area facing southward.





Photo 4. View of the reference area comprised of mixed ponderosa pine, and pinyon and juniper woodland, with and understory of gambel oak, black sagebrush, mountain mahogany, western wheatgrass, muttongrass, and threadleaf sunflower.