

Inspection Photos  
Location Name: Cooper 1  
Location ID: 318519



Photo 1 WH/sign

Photo 2 TB sign

**Inspection Photos**  
**Location Name: Cooper 1**  
**Location ID: 318519**



**Photo 3 TB**



**Photo 4 Vertical Heated Sep.**

# Inspection Photos

Location Name: Cooper 1  
Location ID: 318519




Photo 5 Gas Meter Run

Photo 6 Card in meter house indicates current calibration



**Inspection Photos**  
**Location Name: Cooper 1**  
**Location ID: 318519**



**Photo 7 weeds have been cut around location**