

# Inspection Photos

11/19/2021

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 311696

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location ID: 311696



**Photo 1:** Photos taken from the cut slopes along the east end of the Location. Photos provide example showing Operator has placed a single row of straw wattle along portions of the cut slope. Soils along cut slopes remain loose and unstabilized. Control measures to manage runoff, and to protect and stabilize slopes of the Location remain missing or insufficient.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location ID: 311696



**Photo 2:** Photos taken from the cut slopes along the east end of the Location. Photos provide example showing Operator has placed a single row of straw wattle along portions of the cut slope. Soils along cut slopes remain loose and unstabilized. Control measures to manage runoff, and to protect and stabilize slopes of the Location remain missing or insufficient.



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 311696



**Photo 3:** Photos taken from the fill slopes along the west end of the Location. Unable to find evidence that work was conducted to address stormwater and erosion degradation issues at the slopes on the west end of the Location. Control measures to manage runoff, and to protect and stabilize slopes of the Location remain missing or insufficient.