

Inspection Photos

API: 071-06191

Operator: OGRIS OPERATING LLC

Inspection Date: 11/19/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06191 | Date: 11/19/2021

Inspection Photos



Photo 1. The cattle guard along the main road near the Bingham campground has been repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06191 | Date: 11/19/2021

Inspection Photos



Photo 2. The culverts along the main road have been cleaned out and repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06191 | Date: 11/19/2021

Inspection Photos



Photo 3. Facing southwest. The road was regraded and additional gravel was spread along areas of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06191 | Date: 11/19/2021

Inspection Photos



Photo 4. Facing northwest along the access road. This area of the road was repaired. There is water seeping near the road due to a beaver dam upstream. This area may need to be reconstructed to allow water flow during high stream flow periods (e.g. culvert).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06191 | Date: 11/19/2021

Inspection Photos



Photo 5. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06191 | Date: 11/19/2021