

Inspection Photos

API: 071-06347

Operator: OGRIS OPERATING LLC

Inspection Date: 11/19/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06347 | Date: 11/19/2021

Inspection Photos



Photo 1. The road was regraded and additional gravel was spread along areas of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06347 | Date: 11/19/2021

Inspection Photos



Photo 2. The culvert near the location has been cleaned out and repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06347 | Date: 11/19/2021

Inspection Photos



Photo 3. Facing toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06347 | Date: 11/19/2021