

Inspection Photos

API: 071-08927

Operator: OGRIS OPERATING LLC

Inspection Date: 11/19/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08927 | Date: 11/19/2021

Inspection Photos



Photo 1 Facing south at the location. The bare soils on the flat portion have been seeded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08927 | Date: 11/19/2021

Inspection Photos



Photo 2. Facing toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08927 | Date: 11/19/2021