

Final Reclamation Inspection

November 11, 2021

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 336222

Inspection Document #: 697503512

Weld County, CO

SWSE Section 25 T2N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HSR-RUSSELL #15-25A
Location ID: 336222



Photo 1. Photo taken from the well location, facing South. Photo illustrates that the well location is reflective of reference area vegetative levels.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: HSR-RUSSELL #15-25A
Location ID: 336222



Photo 3. Photo taken from the well location, facing North. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos

Location Name: HSR-RUSSELL #15-25A

Location ID: 336222



Photo 5. Photo taken from the associated offsite tank battery, facing East. Photo illustrates the tank battery is still in use for other active wells.



Photo 6. Photo taken from the associated offsite tank battery, facing North. See comments under Photo 5.